



Shop: Pristine Auto

Tel:

Test Time: 2024-06-07 08:01:55

Technician: --

BMW Vehicle Diagnostic Report

Vehicle Information
--/BMW/X'/X3 M40i_B58/B58
VIN: 5UX83DP01R9V55800

Customer Information

Name: --

Device information Scanner: MaxiSys Ultra Version: V13.21 Odometer Reading: 6450 km License Plate:

Tel:

🔁 System Scanned(35)

System	S	tatus/DTC
DME (Engine-Digital Motor Electronics)		② 0
EGS (Electronic Transmission Management)		② 0
VTG (Transfer Box)		② 0
DSC (Dynamic Stability Control)		② 0
ACSM (Airbag-Advanced Crash Safety Module)		② 0
KOMBI (Instrument Cluster)		② 0
HRSNL (Left Rear Radar Sensor Near Range)	APAS	② 0
SRSNVR (Right Front Side Radar Sensor Near Range)	APAS	② 0
BDC (Body Domain Controller)		② 0
BATT48 (Battery electronics 48 volt)		② 0
TRSVC (All Round View Camera)	APAS	② 0
HRSNR (Right Rear Radar Sensor Near Range)	APAS	② 0
HKFM (Rear Tailgate Function Module)		② 0
ZGM (Central Gateway Module)		② 0
FRSF (Long-distance range front radar sensor)	APAS	② 0



www.autel.com MaxiSys Ultra Pag

	Report ID: MAXIA20240607080155
SAS2 (Optional Equipment System 2)	Q 1
SRSNVL (left Front Side Radar Sensor Near Range)	② 0
PMA (Parking Maneuvering Assistant)	⊘ 0
/BMW/X'/X3 M40i_B58/B58 Test Time: 2024-06-07 08:0	1:55
EPS (Electric Power Steering)	② 0
RAM (Receiver audio module)	○ 0
VIP (Virtual integration system)	② 0
FLEL (Frontal Light Electronics Left)	○ 0
FLER (Frontal Light Electronics Right)	⊘ 0
DCS (Driver Camera System)	⊘ 0
PCU48 (Power Control Unit 48V)	⊘ 0
SGR48 (Starter motor generator 48 volt)	⊘ 0
FZD (Roof Function Center)	⊘ 0
KAFAS (Camera-Based Driver-Assistance Systems)	⊘ 0
GWS (Gear Selector Switch)	⊘ 0
TCB (Combox Emergency Call)	⊘ 0
HUH (Headunit High)	⊘ 0
CON (Controller)	② 0
SMFA (Driver Seat Module)	⊘ 0
VDP (Vertical dynamics platform)	② 0
IHKA (Integrated Automatic Heating And A/C System)	② 0
DTC (1) SAS2 (Optional Equipment System 2) (1 DTC)	
DTC Description	Status

www.autel.com MaxiSys Ultra Page 2

			Report ID:	MAXIA20240607080155
D1D47D		data function of alertness assistant, 251.3.8) invalid, ter ACSM	Intermi	ttent
'BMW/X'/X3 M40i_	B58/B58	Test Time: 2024-06-07 08:01:55		
Technician No	rtes			
		Customer		
		name:		

Technician: Date:

Note:Please save a copy of this report for your records.



www.autel.com MaxiSys Ultra Pag

Report ID: MAXIA20240607080155

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys Ultra www.autel.com Page 4